



**RENAULT Megane: 1EHL210**

Vinnnumber:	<b>VF1KZ1A0748050378</b>	Versionname:	<b>MEGANE GT TomTom Edition 90PK</b>
First Registrationdate:	<b>4/12/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>147872</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Break</b>	Body color	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1433</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Summer tyres:	Fr.L.	<b>Firestone: 2 mm</b>	Fr.R.	<b>Firestone: 2 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	<b>1984,10</b>
-------------------	----------------

Door F R, Scratch(es), It - Spot repair	<b>115,56</b>
---	---------------



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>318,35</b>
---	---------------



Wing R R, Bump(s) and scratch(es), Le - Replace and paint	<b>0,00</b>
---	-------------



Wheel cover F R, Scratch(es), E - Replace 30,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Roof pillar R, Bump(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Dirty, Cleaning 100,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Rearview mirror housing R, Damaged, E - Replace 44,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Wing R L, Bump(s), PDR - Knock out without painting 63,00



Door F L, Scratch(es), It - Spot repair 115,56



Wheel cover R L, Scratch(es), E - Replace 30,00



Bumper grille, Damaged, E - Replace 64,00



Wheel cover F L, Scratch(es), E - Replace 30,00

