



PEUGEOT 208: WZ4697

Vinnnumber:	VF3CC8HR0CW140264	Versionname:	208 BER Access 68PK
First Registrationdate:	6/01/2016	Fiscalpower:	
Expertise Mileage:	144567	Power Kw:	50
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	BINNEN 1500KM	Parking lot	1118
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Luggage cover	
Windows electric F			
Cruise Control			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	185/65/15/88 T Steel			
Winter tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm

Assistance equipment


Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	932,48
-------------------	---------------

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	217,44
---	---------------



Door R L, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Wheel cover R L, Damaged, E - Replace	24,00
---------------------------------------	--------------



Wing R R, Bump(s), PDR - Knock out without painting 63,00



Floor covering F L, Tear, E - Replace 240,00



Door F R, Damaged, Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 217,44



Wheel cover R R, Damaged, E - Replace 24,00



Wheel cover F R, Damaged, E - Replace 24,00



Engine protective plate, Tear, E - Replace 59,60

