



VOLVO XC60: 1GAL898			
Vinnumber:	YV1DZ3150E2565588	Versionname:	XC60 D3 Kinetic Geartr.136PK Aut.
First Registrationdate:	6/12/2013	Fiscalpower:	
Expertise Mileage:	82749	Power Kw:	100
Bodytype:		Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2122
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Seats electric F L
GPS storage HD	Central consol F
GPS storage	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting Headlighting Halogen	
Type of GPS GPS big screen color	
Type of Lining Lining leather	
Type of climate control Autom climate control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	235/65/17/101 H LightMetal			
	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment	
Spare tyre compact	Yes Jack Yes
Total cost ex VAT	1903,47
Roof pillar R, Chemical polution, Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Chemical polution, LI - Repair and paint (complete)	264,21



Roof, Chemical polution, LI - Repair and paint (complete)	577,80
---	--------



Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Chemical polution, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16



Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
---	--------



Door F R, Chemical polution, LI - Repair and paint (complete)	264,21
---	--------





Wing R L, Chemical polution, Acceptable	0,00
---	------

No pictures to display

Daytime running lights R, Damaged, E - Replace	100,00
--	--------

