


**SKODA Octavia: 1FUA211**

|                                    |                          |              |                                     |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnnumber:                        | <b>TMBJG9NEXE0082609</b> | Versionname: | <b>OCTAVIA COMBI Ambition 105PK</b> |
| First Registrationdate:            | <b>24/10/2013</b>        | Fiscalpower: |                                     |
| Expertise Mileage:                 | <b>116549</b>            | Power Kw:    | <b>77</b>                           |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Silver</b>                       |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                      |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                           |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1120</b>                         |
| Number of doors:                   | <b>5</b>                 |              |                                     |
| Number of seats:                   | <b>5</b>                 |              |                                     |
| Number head rests:                 | <b>5</b>                 |              |                                     |
| Rims summer:                       | <b>Aluminium</b>         |              |                                     |
| Category:                          | <b>Passenger Car</b>     |              |                                     |
| Oil level:                         | <b>OK</b>                |              |                                     |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                     |

**Options**

|                                |                              |                       |                          |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Radio CD                       |                              | Central consol F      |                          |
| GPS storage                    |                              | Luggage cover         |                          |
| GPS storage                    | <b>HD</b>                    | Front parking sensors |                          |
| Windows electric F             |                              | Rear parking sensors  |                          |
| Windows electric R             |                              | Type of Tow bar       | <b>Tow bar removable</b> |
| Cruise Control                 |                              |                       |                          |
| Steering wheel multifunctional |                              |                       |                          |
| Seats F heated                 |                              |                       |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                          |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                          |
| Type of climate control        | <b>Autom climate control</b> |                       |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/91 V LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|               | Re.L.                            | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|   |       |
|---|-------|
| Total cost ex VAT                                   | 63,00 |
| Bonnet, Stone chip(s), Acceptable                   | 0,00  |
| <i>No pictures to display</i>                       |       |
| Door R R, Scratch(es), Acceptable                   | 0,00  |
| <i>No pictures to display</i>                       |       |
| Trunk lid covering R, Scratch(es), Acceptable       | 0,00  |
| <i>No pictures to display</i>                       |       |
| Bonnet, Scratch(es), Acceptable                     | 0,00  |
| <i>No pictures to display</i>                       |       |
| Door R L, Bump(s), PDR - Knock out without painting | 63,00 |



|                                       |      |
|---------------------------------------|------|
| Windscreen, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i>         |      |
| Bumper R, Scratch(es), Acceptable     | 0,00 |
| <i>No pictures to display</i>         |      |