


SKODA Octavia: 1BOP699

Vinnnumber:	TMBHT21Z0C2018722	Versionname:	OCTAVIA COMBI Ambiente
First Registrationdate:	19/07/2011	Fiscalpower:	DPF 105PK
Expertise Mileage:	204594	Power Kw:	77
Bodytype:	Break	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3203
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/15/91 T LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------



Total cost ex VAT 996,86

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

Bonnet, Bump(s), LI - Repair and paint (complete) 290,08

Dashboard, Scratch(es), Acceptable 0,00

No pictures to display
Wing R R, Bump(s), Acceptable 0,00

<i>No pictures to display</i>		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
Bodywork, Not original part, Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Bump(s), PDR - Knock out without painting		63,00
		
Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)		220,18
		