



SEAT Alhambra: 1GDI437

Vinnumber:	VSSZZZ7NZEV511505	Versionname:	ALHAMBRA Eco.Tech.Styl.DPF DSG 136PK Aut
First Registrationdate:	7/01/2014	Fiscalpower:	100
Expertise Mileage:	187928	Power Kw:	100
Bodytype:	MAN 6 VIT	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1406
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Fulda: 8 mm	Re.R.	Fulda: 8 mm

Assistance equipment

Total cost ex VAT	1260,32
Internal Boot Lining L, Damaged, E - Replace	223,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

254,16





Door F L, Bump(s), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Internal Boot Lining R, Damaged, E - Replace 223,00



Foglight R, Broken, E - Replace 156,00



Windscreen, Repaired, Acceptable 0,00



Interior, Dirty, Cleaning 150,00

