



VOLKSWAGEN TIGUAN: 1DG5991

Vinnnumber:	WVGZZ5NZCW093355	Versionname:	TIGUAN 4M Sport&Style BM Tech.140PK
First Registrationdate:	11/05/2012	Fiscalpower:	
Expertise Mileage:	114449	Power Kw:	103
Bodytype:	SUV	Body color:	Green
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2424
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage		Sun Roof electric	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	235/55/17/99 V LightMetal			
Winter tyres:	Fr.L.	Pirelli: 2 mm	Fr.R.	Pirelli: 2 mm
	Re.L.	Continental: 2 mm	Re.R.	Continental: 2 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 638,52

Tailgate, Rust, LI - Repair and paint (complete) 301,68



Bumper corner R R, Scratch(es), Smart repair 110,64



Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper corner R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing moulding F R, Scratch(es), E - Replace	14,40



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

