



## VOLKSWAGEN Passat: 1EJR62Z

|                         |                          |              |   |
|-------------------------|--------------------------|--------------|---|
| Vinnnumber:             | <b>WVWZZZ3CZDP029127</b> | Versionname: | <b>PASSAT BER Comfortline BMT 105PK</b> |
| First Registrationdate: | <b>1/01/2013</b>         | Fiscalpower: |   |
| Expertise Mileage:      | <b>132535</b>            | Power Kw:    | <b>77</b>                               |
| Bodytype:               | <b>Berline</b>           | Body color:  | <b>Black</b>                            |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                          |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                        |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                               |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>3723</b>                             |
| Number of doors:        | <b>4</b>                 |              |   |
| Number of seats:        | <b>5</b>                 |              |   |
| Number head rests:      | <b>5</b>                 |              |   |
| Rims summer:            | <b>Aluminium</b>         |              |   |
| Category:               | <b>Passenger Car</b>     |              |   |
| Oil level:              | <b>OK</b>                |              |   |

## Options

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Front parking sensors        |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting:          | <b>Headlighting Halogen</b>  |
| Type of GPS:                   | <b>GPS big screen color</b>  |
| Type of Lining:                | <b>Lining fabrics</b>        |
| Type of climate control:       | <b>Autom climate control</b> |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

## Degree of wear

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/55/16/91 V LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Goodyear: 4 mm</b> | Fr.R. | <b>Goodyear: 4 mm</b> |
|               | Re.L.                            | <b>Goodyear: 5 mm</b> | Re.R. | <b>Goodyear: 5 mm</b> |

## Assistance equipment

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 274,80 |
|-------------------|--------|


|                               |      |
|-------------------------------|------|
| Tailgate, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

|                                       |      |
|---------------------------------------|------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

|   |       |
|---|-------|
| Door F L, Bump(s), PDR - Knock out without painting | 63,00 |
|---|-------|



|   |        |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|

