



## VOLKSWAGEN Touran: 1FKC004

Vinnnumber:	<b>WVGZZ1TZEW013009</b>	Versionname:	<b>TOURAN Trendline BMT St/St DSG 105PK Aut</b>
First Registrationdate:	<b>23/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>104544</b>	Power Kw:	<b>77</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Dark Green</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2705</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Rear parking sensors	
Type of GPS	<b>GPS big screen color</b>	Type of Tow bar	<b>Tow bar removable</b>
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Kleber: 6 mm</b>	Fr.R.	<b>Kleber: 6 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>115,56</b>
-------------------	---------------

Door R R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Alloy rim F R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Wing R L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Bumper R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Front bumper, Scratch(es), It - Spot repair	<b>115,56</b>
---	---------------

