



MINI Mini: 1GCN959			
Vinnnumber:	WMWSW11040T771164	Versionname:	MINI One D 90PK DPF
First Registrationdate:	2/01/2014	Fiscalpower:	
Expertise Mileage:	102280	Power Kw:	66
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2703
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-leather
Type of climate control:	Autom climate control



Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	175/65/15/84 T LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			598,76
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Scratch(es), LI - Repair and paint (complete)			308,20

Windscreen, Stone chip(s), Acceptable			0,00

Door F L, Scratch(es), Acceptable			0,00

<i>No pictures to display</i>		
Interior, Dirty, Cleaning		25,00
		
Wing R L, Scratch(es), It - Spot repair		115,56
		
Wing R R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Ignition key, Missing, E - Replace		150,00
<i>No pictures to display</i>		