



**VOLVO V60: 1GJE590**

Vinnumber:	<b>YV1FW8481E1197886</b>	Versionname:	<b>V60 BRE D2 Kinetic 115PK</b>
First Registrationdate:	<b>21/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>106854</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:		Oil level:	<b>NOT OK</b>
Battery functioning:	<b>No</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining leather</b>

**Limited Technical Inspection**

Airco functioning:	<b>NOT OK</b>	Battery functioning:	<b>No</b>
Tires wear profile:	<b>NOT OK</b>	Sound engine:	<b>NOT OK</b>
Idle position:	<b>NOT OK</b>	Clutch test:	<b>NOT OK</b>
Engine startingtime:	<b>NOT OK</b>	Wiper fluid level:	<b>NOT OK</b>
Exhaust gass:	<b>NOT OK</b>	Lighting:	<b>NOT OK</b>
Transmission:	<b>NOT OK</b>	Wiperblades:	<b>NOT OK</b>
Handbrake:	<b>NOT OK</b>		

**Degree of wear**

	<b>215/55/17/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 2 mm</b>	Fr.R.	<b>Michelin: 2 mm</b>
	Re.L.	<b>Michelin: 2 mm</b>	Re.R.	<b>Michelin: 2 mm</b>

**Assistance equipment**

Total cost ex VAT	0,00
Bodywork, Damaged, P - Check	0,00



