



## VOLKSWAGEN Passat: 1EJR640

|                         |                          |              |                               |
|-------------------------|--------------------------|--------------|-------------------------------|
| Vinnnumber:             | <b>WVWZZZ3CZDE100286</b> | Versionname: | <b>PASSAT BER Comfortline</b> |
| First Registrationdate: | <b>1/01/2013</b>         | Fiscalpower: | <b>DSG 140PK Aut.</b>         |
| Expertise Mileage:      | <b>137635</b>            | Power Kw:    | <b>103</b>                    |
| Bodytype:               | <b>Berline</b>           | Body color   | <b>Dark Brown</b>             |
| Gearbox:                | <b>Automatic</b>         | Paint type   | <b>Metalic</b>                |
| Transmission:           | <b>Front</b>             | Rims summer  | <b>Aluminium</b>              |
| Fueltype:               | <b>Diesel</b>            | Oil level    | <b>OK</b>                     |
| Battery functioning     | <b>Yes</b>               | Parking lot  | <b>2432</b>                   |
| Number of doors         | <b>4</b>                 |              |                               |
| Number of seats         | <b>5</b>                 |              |                               |
| Number head rests       | <b>5</b>                 |              |                               |
| Rims summer             | <b>Aluminium</b>         |              |                               |
| Category                | <b>Passenger Car</b>     |              |                               |
| Oil level               | <b>OK</b>                |              |                               |

## Options

|                         |                              |
|-------------------------|------------------------------|
| Radio CD                | Central consol F             |
| Windows electric F      | Luggage cover                |
| Windows electric R      | Front parking sensors        |
| Cruise Control          | Rear parking sensors         |
| Radio multimedia        |                              |
| Type of headlighting    | <b>Headlighting Halogen</b>  |
| Type of GPS             | <b>GPS big screen color</b>  |
| Type of Lining          | <b>Lining fabrics</b>        |
| Type of climate control | <b>Autom climate control</b> |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

## Degree of wear

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>215/55/16/97 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Bridgestone: 4 mm</b> | Fr.R. | <b>Bridgestone: 4 mm</b> |
|               | Re.L.                            | <b>Bridgestone: 5 mm</b> | Re.R. | <b>Bridgestone: 5 mm</b> |

## Assistance equipment

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|   |               |
|---|---------------|
| Total cost ex VAT                                       | <b>915,23</b> |
| Door R R, Scratch(es), LI - Repair and paint (complete) | <b>318,35</b> |




|  |              |
|--|--------------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--|--------------|



|   |             |
|---|-------------|
| Boot carpet, Waterinfiltration, P - Check | <b>0,00</b> |
|---|-------------|

No pictures to display

|   |               |
|---|---------------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | <b>290,08</b> |
|---|---------------|



|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|   |        |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|

