


BMW 5: 1GFH474

Vinnnumber:	WBA5J11010D335751	Versionname:	5 TOURING 518d 136PK
First Registrationdate:	23/01/2014	Fiscalpower:	
Expertise Mileage:	183288	Power Kw:	100
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1630
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

225/55/17/101 V LightMetal				
Winter tyres:	Fr.L.	Semperit: 3 mm	Fr.R.	Semperit: 3 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	362,02
-------------------	--------

Tailgate, Damaged, LI - Repair and paint (complete)	362,02
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display