



AUDI A3: 1ELW795			
Vinnnumber:	<b>WAUZZ8P7DA063189</b>	Versionname:	<b>A3 SB Attract.St./St.DPF S-tr.105PK Aut.</b>
First Registrationdate:	<b>17/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>81274</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2523</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>
	Rear parking sensors

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
		Jack	<b>Yes</b>

Total cost ex VAT	<b>1757,68</b>
Door F R, Scratch(es), LI - Repair and paint (complete)	<b>318,35</b>



Alloy rim F L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>



Wing F L, Scratch(es), LI - Repair and paint (complete)	<b>220,18</b>
---------------------------------------------------------	---------------



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing L, Damaged, E - Replace 74,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Windscreen, Stone chip(s), Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

