



BMW 3: 1ELW778

Vinnumber:	WBA3D110X0F326548	Versionname:	3 BER 318d 136PK
First Registrationdate:	17/01/2013	Fiscalpower:	
Expertise Mileage:	108517	Power Kw:	100
Bodytype:		Body color:	WIT
Gearbox:	MAN 6 VIT	Body color:	White
Transmission:	Back	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	OK	Oil level:	OK
Maintenance:	15/01/2018	Parking lot:	1328
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio multimedia		Central consol F	
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1172,69
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18
--	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
--	---------------



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

