



| AUDI A6: 1FKZ170        |                          |              |                                    |
|-------------------------|--------------------------|--------------|------------------------------------|
| Vinnnumber:             | <b>WAUZZZ4G9EN032087</b> | Versionname: | <b>A6 AVANT Multitr.136PK Aut.</b> |
| First Registrationdate: | <b>1/08/2013</b>         | Fiscalpower: |                                    |
| Expertise Mileage:      | <b>190003</b>            | Power Kw:    | <b>100</b>                         |
| Bodytype:               | <b>Break</b>             | Body color:  | <b>White</b>                       |
| Gearbox:                | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                     |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                   |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                          |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>3732</b>                        |
| Number of doors:        | <b>5</b>                 |              |                                    |
| Number of seats:        | <b>5</b>                 |              |                                    |
| Number head rests:      | <b>5</b>                 |              |                                    |
| Rims summer:            | <b>Aluminium</b>         |              |                                    |
| Category:               | <b>Passenger Car</b>     |              |                                    |
| Oil level:              | <b>OK</b>                |              |                                    |

| Options                        |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional |                              |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position                | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission                 | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake                    | <b>OK</b> |                     |            |

| Degree of wear |                                  |                       |       |                       |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| Winter tyres:  | <b>225/55/17/97 H LightMetal</b> |                       |       |                       |
|                | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|                | Re.L.                            | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

| Assistance equipment  |                |            |            |
|---|----------------|------------|------------|
| Repair kit  | <b>Yes</b>     | Compressor | <b>Yes</b> |
| Total cost ex VAT   | <b>2897,34</b> |            |            |
| Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | <b>0,00</b>    |            |            |



|  |              |
|--|--------------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--|--------------|




|   |               |
|---|---------------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | <b>254,16</b> |
|---|---------------|



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 348,09



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), It - Spot repair 115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), Le - Replace and paint 1429,81



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16

