



**BMW 3 TOURING: 1NGN412**

Vinnumber:	<b>WBA3K11050F823884</b>	Versionname:	<b>2.0 318D (100KW) TOURING</b>
First Registrationdate:	<b>6/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>135864</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1232</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>HD</b>
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/50/17/94 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Runflat	<b>Yes</b>
---------	------------

Total cost ex VAT	<b>2111,80</b>
Seat cover F L, Damaged, Acceptable	<b>0,00</b>



Wing trim R L, Bump(s), E - Replace	<b>84,00</b>
-------------------------------------	--------------



Roof, Hail damage, PDR - Hail 1325,00



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Door R L, Bad repair, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Door trim F L, Bump(s), E - Replace 114,00



Door R R, Bump(s), PDR - Knock out without painting 63,00



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Door panel F R, Damaged, E - Replace 114,00



Door F L, Bad repair, Acceptable 0,00



Bonnet, Hail damage, PDR - Hail 200,00

