



BMW 114: 1JLP893

| | | | |
|------------------------------------|-----------------------------------|--------------|------------------|
| Vinnumber: | WBA1T91040P978696 | Versionname: | DIESEL |
| First Registrationdate: | 19/01/2015 | Fiscalpower: | |
| Expertise Mileage: | 43376 | Power Kw: | 70 |
| Bodytype: | Hatchback | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OVERSCHREDEN SINDS 11 2017 | Parking lot: | 3828 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|---------------------|-------|---------------------|
| | 205/55/16/91 W LightMetal | | | |
| Summer tyres: | Fr.L. | Dunlop: 6 mm | Fr.R. | Dunlop: 6 mm |
| | Re.L. | Dunlop: 5 mm | Re.R. | Dunlop: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|--------------|
| Total cost ex VAT | 75,00 |
|-------------------|--------------|

| | |
|---|-------------|
| Rocker panel inner R L, Scratch(es), Acceptable | 0,00 |
|---|-------------|




| | |
|-------------------------------------|-------------|
| Maintenance, Maintenance, P - Check | 0,00 |
|-------------------------------------|-------------|



Seat cover F L, Stain, Cleaning

25,00



Seat cover R, Stain, Cleaning

50,00

