



BMW 3: 1HEX925

Vinnumber:	WBA3D11010J627688	Versionname:	3 BER 318d 136PK
First Registrationdate:	3/07/2014	Fiscalpower:	
Expertise Mileage:	203906	Power Kw:	100
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2705
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

	Runflat	Yes
--	---------	------------

Total cost ex VAT	1579,26
-------------------	----------------

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Rearlight L, Damaged, E - Replace	114,00
-----------------------------------	---------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00




Ignition key, Missing, E - Replace 150,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Wing F L, Chemical polution, LI - Repair and paint (complete) 220,18



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

