



BMW 1: 1FSH958

Vinnnumber:	WBA1C71060J946551	Versionname:	1 BER HATCH 116d 116PK
First Registrationdate:	9/10/2013	Fiscalpower:	
Expertise Mileage:	138638	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3509
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1483,37
--------------------------	----------------

Bumper R, Bump(s) and scratch(es), Le - Replace and paint	651,00
--	---------------



Headlight R, Scratch(es), 67 - Polish	55,19
--	--------------



Door F R, Bump(s), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, E - Replace 360,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display


Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bad repair, P - Check 0,00



Roof, Scratch(es), 67 - Polish 55,19



Bonnet, Chemical polution, 67 - Polish 55,19

