







95,00

## BMW 5: 1GC \$570

Vinnumber: WBA5C11090D033649 First Registrationdate: 2/01/2014 Expertise Mileage: 138135 Power Kw: Bodytype: Berline Gearbox: Automatic Transmission: Back Fueltype: Diesel Battery functioning Yes Number of doors 4 Number of seats 5 Number head rests 5 Rims summer Aluminium Category Passenger Car Oil level ок

Registration Certificate Car (BE)

Versionname: 5 BER 518dA 136PK Aut.

Fiscalpower:

100 Body color Dark Grey Paint type Metalic Rims summer Aluminium Oil level OK Parking lot 3304

## Options

Radio CD Seats electric F L Windows electric F Seats electric F R Windows electric R Sun Roof electric Cruise Control Front parking sensors Steering wheel multifunctional Seats F heated Rear parking sensors

Yes

Radio multimedia

Type of headlighting Headlighting Xenon Type of GPS GPS big screen color Type of Lining Lining leather Type of climate control **Autom climate** control Head-up Display

## **Limited Technical Inspection**

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	ОК	Sound engine	ок
Idle position	ок	Clutch test	ок
Engine startingtime	ок	Wiper fluid level	ок
Exhaust gass	ок	Lighting	ок
Transmission	ок	Wiperblades	ок
Handbrake	ок		

## Degree of wear

	225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm	
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm	

Assis	tance	equi	pme	nt	

Total cost ex VAT	95,	
Bumper R, Scratch(es), Acceptable	0,00	
No pictures to display		





Alloy rim R L, Scratch(es), LI - Repair and paint (complete)