


**MERCEDES B: 1EMW221**

Vinnumber:	<b>WDD2462001J140337</b>	Versionname:	<b>B 180 CDI BE 109PK</b>
First Registrationdate:	<b>25/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>132581</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2811</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	725,98
-------------------	--------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Protection plate M, Tear, E - Replace	74,00
---------------------------------------	-------

Protection plate m, rear, E - Replace 75,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Wheel cover R L, Scratch(es), E - Replace 30,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Interior, Dirty, Cleaning 100,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18

