



LEXUS NX: 1LPL403

Vinnumber:	JTJBJRBZX02029478	Versionname:	300H
First Registrationdate:	5/11/2015	Fiscalpower:	
Expertise Mileage:	50340	Power Kw:	145
Bodytype:		Body color:	Red
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	1624
Maintenance	LAATST OH OP 48.049 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/60/18/100 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 8 mm	Re.R.	Pirelli: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2533,80
-------------------	---------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Backrest cover F L, Worn, Acceptable	0,00
--------------------------------------	------

No pictures to display

Armrest F Mid, Tear, E - Replace	850,00
----------------------------------	--------



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door F R, Scratch(es), 67 - Polish 55,19



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Rocker panel inner F L, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper trim R, Scratch(es), Smart repair 110,64



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, P - Check 0,00



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 288,21



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing trim R R, Scratch(es), E - Replace 96,00

