



**CITROEN C4 Picasso: 1ENP392**

Vinnnumber:	<b>VF7UA9HR8DJ511608</b>	Versionname:	<b>GR.C4 PICASSO 7pl.Excl.BMP FAP 112PK Aut</b>
First Registrationdate:	<b>31/01/2013</b>	Fiscalpower:	<b>82</b>
Expertise Mileage:	<b>115402</b>	Power Kw:	<b>82</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1112</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**











	<b>215/55/16/93 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Total cost ex VAT	2763,31
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

	Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
		
		
	Windscreen, Damaged, E - Replace	0,00
	Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
	Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
	Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
	Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
	Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
	Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Seat cover F R, Dirty, Cleaning	25,00
		
	Roof, Bump(s) and scratch(es), LI - Repair and paint (complete)	481,50



Bumper corner R R, Scratch(es), It - Spot repair 0,00



Ignition key, Missing, E - Replace 150,00

*No pictures to display*