



FORD Fiesta: PR8786

Vinnumber:	WF0DXXGAKDDC60464	Versionname:	FIESTA BER Trend 75PK
First Registrationdate:	26/09/2013	Fiscalpower:	
Expertise Mileage:	111093	Power Kw:	55
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3224
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/50/15/82 H Steel			
Winter tyres:	Fr.L.	Goodyear: 8 mm	Fr.R.	Goodyear: 8 mm
	Re.L.	Goodyear: 8 mm	Re.R.	Goodyear: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	3598,20
Roof, Bump(s) and scratch(es), LI - Repair and paint (complete)	529,20



Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 217,44



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 390,56



Wheel cover F R, Scratch(es), E - Replace 24,00



Aerial, Missing, E - Replace 12,00



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 328,06



Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Door F L, Bump(s), PDR - Knock out without painting 63,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56

Wing R R, Scratch(es), LI - Repair and paint (complete) 240,00



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 398,68



Door F R, Scratch(es), LI - Repair and paint (complete) 254,68



Windscreen, Scratch(es), E - Replace 413,76



Wheel cover F L, Scratch(es), E - Replace 24,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 272,14

