



HYUNDAI I40: 1EHO977			
Vinnnumber:	<b>KMHLB81UACU040748</b>	Versionname:	<b>i40 BRE Lounge ISG 115PK</b>
First Registrationdate:	<b>5/12/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>150159</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2625</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>HD</b> Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>NOT OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>NOT OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 6 mm</b>	Fr.R.	<b>Uniroyal: 6 mm</b>
	Re.L.	<b>Uniroyal: 6 mm</b>	Re.R.	<b>Uniroyal: 6 mm</b>

Assistance equipment	
Spare tyre compact	<b>Yes</b> Jack <b>Yes</b>
Total cost ex VAT	987,24
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Bonnet, Rust, LI - Repair and paint (complete) 290,08



Alloy rim F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Bump(s), PDR - Knock out without painting 63,00



Alloy rim R R, Scratch(es), Acceptable 0,00

*No pictures to display*