


FORD GRAND C-MAX: 1FXJ917

Vinnumber:	WFOHXXWPBHDK62127	Versionname:	D
First Registrationdate:	27/11/2013	Fiscalpower:	
Expertise Mileage:	133822	Power Kw:	84
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2315
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	2448,85
-------------------	---------

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------



Rearlight R , Broken, E - Replace 114,00



Grill, Damaged, Smart repair 110,64



Bumper moulding R, Bump(s) and scratch(es), E - Replace 14,40



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 259,80




Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 268,18



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Rearlight L tailgate, Broken, E - Replace 148,15



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35

