



**FORD Tourneo Custom: HK4417**

Vinnnumber:	<b>WF03XTTG3EL46105</b>	Versionname:	<b>TOURNEO CUSTOM 3005 SWB Limited 125PK</b>
First Registrationdate:	<b>1/03/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>122584</b>	Power Kw:	<b>92</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1210</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>9</b>		
Number head rests:	<b>9</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L
GPS storage		Central consol F
GPS storage	<b>SD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**


	<b>215/65/16/109 R LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 8 mm</b>	Fr.R.	<b>Bridgestone: 8 mm</b>
	Re.L.	<b>Bridgestone: 8 mm</b>	Re.R.	<b>Bridgestone: 8 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>975,93</b>
-------------------	---------------


Tailgate, Bad repair, LI - Repair and paint (complete)	<b>506,02</b>
--	---------------



Wing R R, Bad repair, LI - Repair and paint (complete)	<b>231,15</b>
--	---------------



Door F R, Bad repair, LI - Repair and paint (complete)	238,76
--	--------



Door F L, Bump(s) and scratch(es), Acceptable	0,00
---	------

*No pictures to display*