



FORD Fiesta: PR8789			
Vinnumber:	WF0DXXGAKDDC60477	Versionname:	FIESTA BER Trend 75PK
First Registrationdate:	26/09/2013	Fiscalpower:	
Expertise Mileage:	169115	Power Kw:	55
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3531
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	195/50/15/82 H Steel			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	2133,84
Bonnet, Scratch(es), LI - Repair and paint (complete)	232,06



Roof, Scratch(es), LI - Repair and paint (complete)	385,20
---	--------



Wheel cover R R, Scratch(es), E - Replace 24,00



Wing F L, Incomplete, E - Replace 54,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Wing F R, Scratch(es), LI - Repair and paint (complete) 176,14



Bumper R, Damaged, Le - Replace and paint 535,20



Rearview mirror housing L, Damaged, LI - Repair and paint (complete) 115,56



Wheel cover F R, Scratch(es), E - Replace 24,00



Spoiler R, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel cover F L, Scratch(es), E - Replace 24,00



Door R R, Scratch(es), LI - Repair and paint (complete)	254,68
---	--------



Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover R L, Scratch(es), E - Replace	24,00
---	-------

