



MERCEDES A: 1EYM023			
Vinnumber:	WDD1760121J099021	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	22/04/2013	Fiscalpower:	
Expertise Mileage:	162952	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	NOT OK
Battery functioning:	No		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	NOT OK		
Registration Certificate Car (BE):	No		

Options

Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics

Limited Technical Inspection

Airco functioning:	NOT OK	Battery functioning:	No
Tires wear profile:	NOT OK	Sound engine:	NOT OK
Idle position:	NOT OK	Clutch test:	NOT OK
Engine startingtime:	NOT OK	Wiper fluid level:	NOT OK
Exhaust gass:	NOT OK	Lighting:	NOT OK
Transmission:	NOT OK	Wiperblades:	NOT OK
Handbrake:	NOT OK		

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
-------------	------------	-------------	------------

Total cost ex VAT	0,00
-------------------	-------------

Interior, Damaged, P - Check	0,00
------------------------------	-------------



Bodywork, Accident, No repair	0,00
-------------------------------	-------------



