



PEUGEOT 508: 1GFE278

| | | | |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnnumber: | VF38ERHR8DL060028 | Versionname: | 508 SW Active 136PK |
| First Registrationdate: | 22/01/2014 | Fiscalpower: | |
| Expertise Mileage: | 118652 | Power Kw: | 100 |
| Bodytype: | Break | Body color: | White |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2810 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD | | Panoramic roof | |
| Windows electric F | | Central consol F | |
| Windows electric R | | Luggage cover | |
| Cruise Control | | Front parking sensors | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Type of headlighting | Headlighting Halogen | Type of Tow bar | Tow bar fixed |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |
| Head-up Display | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 215/60/16/99 H LightMetal | | | |
| Winter tyres: | Fr.L. | Goodyear: 5 mm | Fr.R. | Goodyear: 5 mm |
| | Re.L. | Goodyear: 4 mm | Re.R. | Goodyear: 4 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 613,48 |
|-------------------|---------------|

| | |
|----------------------------------|-------------|
| Windscreen, Repaired, Acceptable | 0,00 |
|----------------------------------|-------------|



| | |
|---|---------------|
| Tailgate, Scratch(es), LI - Repair and paint (complete) | 301,68 |
|---|---------------|



| | |
|---|---------------|
| Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|---------------|





| | |
|---------------------------|--------|
| Interior, Dirty, Cleaning | 100,00 |
|---------------------------|--------|

