



<b>RENAULT Clio: 1GDR199</b>			
Vinnumber:	<b>VF15R040H49759360</b>	Versionname:	<b>CLIO IV BER Expression</b>
First Registrationdate:	<b>9/01/2014</b>	Fiscalpower:	<b>75PK</b>
Expertise Mileage:	<b>53621</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1615</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

<b>Options</b>	
Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunction	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>185/55/15/88 T Steel</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 7 mm</b>	Fr.R.	<b>Uniroyal: 7 mm</b>
	Re.L.	<b>Goodyear: 7 mm</b>	Re.R.	<b>Goodyear: 7 mm</b>










<b>Assistance equipment</b>	
Total cost ex VAT	1864,36
Door R L, Scratch(es), LI - Repair and paint (complete)	254,68



Wheel cover R R, Scratch(es), E - Replace	24,00
---	-------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

	Wheel cover F R, Scratch(es), E - Replace	24,00
	Front bumper, Scratch(es), LI - Repair and paint (complete)	169,44
	Wheel cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Certificate Of Conformity, Missing, E - Replace	150,00
<i>No pictures to display</i>		
	Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	246,56
	Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
		
		
	Interior, Dirty, Cleaning	25,00
		
	Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>		
	Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Registration Document, Missing, E - Replace	150,00
<i>No pictures to display</i>		
	Wing R L, Scratch(es), LI - Repair and paint (complete)	246,56
	Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,68
	Wheel cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		