



RENAULT Grand Scenic: 1EKI258

Vinnnumber:	VF1JZ14B648187453	Versionname:	GR.SCENIC Energ.Business
First Registrationdate:	4/01/2013	Fiscalpower:	7pl.FAP 110PK
Expertise Mileage:	142605	Power Kw:	81
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2509
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar removable
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear


	205/60/16/96 H Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	651,96
-------------------	---------------

Door R R, Bump(s), PDR - Knock out without painting	82,80
---	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Interior, Dirty, Cleaning	0,00
---------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), Acceptable 0,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Rear window, Scratch(es), E - Replace 0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56

