



PEUGEOT 508: 1ENS007			
Vinnnumber:	<b>VF38E9HL0DL007921</b>	Versionname:	<b>508 SW Active 115PK</b>
First Registrationdate:	<b>1/02/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>159632</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2725</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining semi-leather</b>
Type of climate control:	<b>Autom climate control</b>
Head-up Display	

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear			
Summer tyres:	<b>215/55/17/96 W LightMetal</b>		
	Fr.L.	Fr.R.	Michelin: 4 mm
	Re.L.	Re.R.	Continental: 4 mm

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	1041,80
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------





Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Ignition key, Missing, E - Replace 150,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Rearview mirror housing R, Scratch(es), Acceptable 0,00

*No pictures to display*

Interior, Dirty, Cleaning 25,00

