



MERCEDES CLASSE CLA: 1HLT816

Vinnumber:	WDD1173121N129480	Versionname:	CLASSE CLA
First Registrationdate:	22/08/2014	Fiscalpower:	
Expertise Mileage:	165379	Power Kw:	80
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1115
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		


Degree of wear


	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1101,80
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Hail damage, PDR - Hail	250,00





Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Hail damage, PDR - Hail 200,00



Roof pillar L, Hail damage, PDR - Hail 200,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Hail damage, PDR - Hail 25,00



Boot carpet, Dirty, Cleaning	25,00
------------------------------	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display