



OPEL ZAFIRA: 1FXP442

Vinnumber:	W0LOAHM75E2029951	Versionname:	
First Registrationdate:	28/11/2013	Fiscalpower:	
Expertise Mileage:	104926	Power Kw:	81
Bodytype:	MPV	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3605
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment


Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT 3401,37

Wheel cover F L, Scratch(es), E - Replace 30,00



Wheel cover F R, Scratch(es), E - Replace 30,00




Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Windscreen, Repaired, P - Check 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Luggage space cover, Missing, E - Replace 240,00



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Front bumper, Damaged, Le - Replace and paint 735,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper grille, No damage, E - Replace 32,40



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35

