



OPEL Astra: 1EJR752			
Vinnnumber:	WOLPD6EA6D1046888	Versionname:	ASTRA BER ecoFLEX Enjoy S&S 95PK
First Registrationdate:	2/01/2013	Fiscalpower:	
Expertise Mileage:	153091	Power Kw:	70
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
GPS storage	Luggage cover
GPS storage	SD Rear parking sensors
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/60/16/95 V Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm







Assistance equipment			
Spare tyre compact	Yes	Jack	Yes

Total cost ex VAT	352,29
Wing F L, Bad repair, P - Check	0,00



Door F R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00



Blinker F R, Broken, E - Replace	39,00
	
Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s), PDR - Knock out without painting	63,00
	
Door R L, Bad repair, P - Check	0,00
	
Bonnet, Chemical polution, 67 - Polish	55,19
	
Rearlight L tailgate, Broken, E - Replace	165,10
	
Door F L, Bad repair, P - Check	0,00
	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	