



VOLVO S60: 1ELJ939			
Vinnnumber:	YV1FS84A1D2211634	Versionname:	S60 BER D2 Kinetic St/St
First Registrationdate:	14/01/2013	Fiscalpower:	115PK
Expertise Mileage:	104953	Power Kw:	84
Bodytype:		Body color	Beige
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1509
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/50/17/95 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	953,78
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Seat cover F L, Stain, Cleaning	25,00
---------------------------------	--------------



Roof, Bump(s), Acceptable	0,00
---------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	--------

