



VOLKSWAGEN Golf: 1GAE836			
Vinnnumber:	WVWZZZAUZEW208729	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	4/12/2013	Fiscalpower:	
Expertise Mileage:	107598	Power Kw:	77
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2304
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		




Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control
Adaptive cruise control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment			
Spare tyre compact	Yes	Jack	Yes

Total cost ex VAT	90,00
Wing R R, Bad repair, Acceptable	0,00

			
Wing F L, Scratch(es), Acceptable			0,00
No pictures to display			
Door R R, Bad repair, Acceptable			0,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Wheel cover R L, Scratch(es), E - Replace 30,00

