



VOLKSWAGEN Beetle: 1DNR289			
Vinnnumber:	WVWZZZ16ZCM652959	Versionname:	BEETLE Design 105PK
First Registrationdate:	2/07/2012	Fiscalpower:	
Expertise Mileage:	131986	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4714
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	235/45/18/98 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			64,32
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R L, Rust, Acceptable			0,00



Wing R R 3P, Bump(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Roof, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R R, Rust, Acceptable			0,00



Alloy rim F R, Rust, Acceptable 0,00



Armrest R M, Hole, Smart repair 64,32



Bonnet, Bump(s), Acceptable 0,00

No pictures to display