



VOLVO S80: 1EKR974			
Vinnumber:	YV1AS84A1D1170441	Versionname:	S80 BER D2 Kinetic S/S
First Registrationdate:	8/01/2013	Fiscalpower:	115PK
Expertise Mileage:	169667	Power Kw:	85
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3709
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment	
Repair kit	Yes Compressor Yes
Total cost ex VAT	349,16
Door R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16

