



**RENAULT Grand Scenic: 1DNB678**

Vinnnumber:	<b>VF1JZ14A647575508</b>	Versionname:	<b>GR.SCENIC Energ.Expression 5Pl.FAP 110PK</b>
First Registrationdate:	<b>27/06/2012</b>	Fiscalpower:	<b>81</b>
Expertise Mileage:	<b>77539</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color	<b>Light Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1713</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	Type of Tow bar
Windows electric R	<b>Tow bar fixed</b>
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>NOT OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/60/16/96 H Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>894,10</b>
-------------------	---------------

Wheel cover F R, Scratch(es), E - Replace	<b>30,00</b>
---	--------------



Wing R L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display	
------------------------	--

Interior, Dirty, Cleaning	<b>100,00</b>
---------------------------	---------------





Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 30,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Door frame F R, Scratch(es), Acceptable 0,00

No pictures to display