



VOLKSWAGEN Golf: 1GEZ735			
Vinnnumber:	WVWZZZAUZEP555416	Versionname:	GOLF VAR Highline 105PK
First Registrationdate:	21/01/2014	Fiscalpower:	
Expertise Mileage:	143457	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1620
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment	
Spare tyre compact	Yes

Total cost ex VAT	495,68
Bumper R, Bump(s) and scratch(es), Le - Replace and paint	0,00



Wing R L, Bump(s) and scratch(es), Le - Replace and paint	0,00
--	------



Seat cover R R, Stain, Cleaning	25,00
--	-------



Rocker panel inner R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

No pictures to display

Protection plate M, Tear, E - Replace	74,00
---------------------------------------	-------



Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------

