



**VOLVO V60: 1DEZ374**

Vinnnumber:	<b>YV1FW84A1C1077508</b>	Versionname:	<b>V60 BRE DRIVe Kinetic Start/Stop 115PK</b>
First Registrationdate:	<b>26/04/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>133118</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Break</b>	Body color:	<b>Light Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1715</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>235/45/17/97 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 5 mm</b>	Fr.R.	<b>Uniroyal: 5 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>1507,00</b>
<b>Bumper R, Scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>



<b>Roof, Bump(s), PDR - Knock out without painting</b>	<b>63,00</b>
--	--------------



<b>Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)</b>	<b>95,00</b>
--	--------------



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Sill outer R, Scratch(es), LI - Repair and paint (complete) 310,50



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35

