



RENAULT TRAFFIC: 1NDF916

Vinnumber:	VF13FL00254856586	Versionname:	
First Registrationdate:	27/01/2016	Fiscalpower:	
Expertise Mileage:	92278	Power Kw:	85
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1306
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Central consol F	
Type of headlighting:	Headlighting Halogen		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/65/16/107 T Steel			
Summer tyres:	Fr.L.	Goodyear: 2,5 mm	Fr.R.	Goodyear: 2,5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1384,52
Ceiling, Burned, Smart repair	64,32



Wheel cover F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Boot carpet, Scratch(es), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Trunk door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	334,76
---	---------------



Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	-------------

No pictures to display

Trunk door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 334,76



Rearview mirror L complete, Scratch(es), Acceptable 0,00

No pictures to display


Bumper R, Bump(s), E - Replace 329,40



Internal Boot Lining R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror R complete, Scratch(es), Smart repair 110,64



Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 100,00



Bumper F R, Scratch(es), Smart repair 110,64



Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display