


**RENAULT Laguna: 1FCY745**

Vinnnumber:	<b>VF1KT1RG649219137</b>	Versionname:	<b>LAGUNA BRE ECO2 Champion Sp.Ed.FAP 110PK</b>
First Registrationdate:	<b>28/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>174403</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Break</b>	Body color	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2130</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/50/17/95 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Fulda: 5 mm</b>	Fr.R.	<b>Fulda: 5 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------


**Total cost ex VAT** 574,80

**Door F R, Scratch(es), Acceptable** 0,00

*No pictures to display*
**Door F L, Bump(s), Acceptable** 0,00

*No pictures to display*
**Bumper R, Scratch(es), Acceptable** 0,00

*No pictures to display*
**Bonnet, Hail damage, PDR - Hail** 275,00

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Interior, Dirty, Cleaning	25,00
---------------------------	-------



Door R L, Bump(s), PDR - Knock out without painting	63,00
---	-------

