



| VOLVO V40: 1NBC568 | | | |
|-----------------------------------|--------------------------|--------------|-----------------------|
| Vinnnumber: | YV1MV74L1G2321092 | Versionname: | 2.0 D2 KINETIC |
| First Registrationdate: | 8/01/2016 | Fiscalpower: | |
| Expertise Mileage: | 38496 | Power Kw: | 88 |
| Bodytype: | | Body color | Light Grey |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 1524 |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

| Options | |
|--------------------------------|-------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Manual climate control |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| Degree of wear | | | | |
|----------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/55/16/94 H LightMetal | | | |
| Winter tyres: | Fr.L. | Continental: 6 mm | Fr.R. | Continental: 6 mm |
| | Re.L. | Continental: 7 mm | Re.R. | Continental: 7 mm |

| Assistance equipment | | | |
|----------------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |

| | |
|---------------------------|---------------|
| Total cost ex VAT | 763,78 |
| Interior, Dirty, Cleaning | 25,00 |



| | |
|---|---------------|
| Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 220,18 |
|---|---------------|



| | |
|--|--------------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

