



VOLKSWAGEN PASSAT I: 1CAE658

Vinnumber:	WVWZZZ3CZCE037750	Versionname:	
First Registrationdate:	3/10/2011	Fiscalpower:	
Expertise Mileage:	122407	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3827
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 V Steel			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1215,03
-------------------	----------------

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------











Bumper R, Bump(s), LI - Repair and paint (complete)	211,80
---	---------------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

<i>No pictures to display</i>		
Bonnet, Chemical polution, LI - Repair and paint (complete)		290,08
		
Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		318,35
		
		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wheel covers (all), Missing, E - Replace		120,00
		
Rearview mirror housing R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing F L, Bump(s), PDR - Knock out without painting		63,00
