



RENAULT Megane: 1FTW120

| | | | |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnnumber: | VF1KZ1A0749793771 | Versionname: | MEGANE BRE Business |
| First Registrationdate: | 23/10/2013 | Fiscalpower: | 90PK |
| Expertise Mileage: | 160109 | Power Kw: | 66 |
| Bodytype: | Break | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1621 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 195/65/15/91 V Steel | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|----------------|
| Total cost ex VAT | 1350,27 |
|-------------------|----------------|

| | |
|---|--------------|
| Wheel cover F R, Scratch(es), E - Replace | 30,00 |
|---|--------------|



| | |
|--------------------------------|---------------|
| Windscreen, Crack, E - Replace | 487,20 |
|--------------------------------|---------------|



| | |
|---|---------------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |
|---|---------------|



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door panel F R, Damaged, E - Replace 114,00



Dashboard, Damaged, Smart repair 110,64



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display