



RENAULT Megane: 1EJR577			
Vinnnumber:	<b>VF1BZ140648195077</b>	Versionname:	<b>MEGANE BER Energy Business 110PK</b>
First Registrationdate:	<b>1/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>121439</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1104</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>195/65/15/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>Continental: 7 mm</b>	Fr.R.	<b>Continental: 7 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	<b>513,60</b>
Wheel cover F L, Scratch(es), E - Replace	<b>30,00</b>











Wheel cover F R, Scratch(es), E - Replace	<b>30,00</b>
---	--------------



Wing R R, Bump(s) and scratch(es), Acceptable	<b>0,00</b>
---	-------------

No pictures to display

Wing R L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

<i>No pictures to display</i>		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
Wheel cover R R, Scratch(es), E - Replace		30,00
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
		
		
Tailgate, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		